girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 10606 Port Bel

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs

5 m,11,30.

# POSTPONED SURVEYS.

Case of the Steel S.S. "WATFORD"

No. 38347 in Reg. Bk. 5741/3303 tons, Built 1938-8

Classed +100A1 4.31 +LMC 8.38 BS 4.31 Owners Watts, Watts & Co. Ld.

Port of Registry London

Survey Due Screwshaft Survey due 8,31.

The Owners state that this vessel is at present trading in the River St. Lawrence, Canada, where she will remain until the end of this year.

They add that they anticipate she will return to this Country early next year when the above survey will be carried out, and they ask that the inspection may be postponed until then.

Submitted for approval
DT 28/9/31

Committee's Minute TUE. 29 SEP 1931

Decision Approved

© 2021 Lloyd's Register Foundation

W696-0105

Survey Fee (per Section 29) £ 15 : 0 : 0

Special Damage or Repair Fee (if any) (per Sec. 29) £ 12 : 12 : 0

Fees applied for, 26 APR 1932 19

Received by me