Rpt. 8. (Received at London Office MON. 16 OCT. 1922) No. 13191.

REPORT of SURVEY for REPAIRS, &c.

WRECK BOX No. 49 Top

Date of writing Report Oct 10. 1922. When handed in at Local Office Oct 10. 1922. Port of Aberdeen.

No. in Reg. Book. 70483. Survey held at Aberdeen. Date, First Survey and Last Survey Oct. 7. 1922. (No. of Visits one.)

on the ~~Wood, Iron or Steel~~ COMPOSITE Sc. Sp. "Portlethen." Master

TONNAGE:— GROSS 146. UNDER DK. 122. NET 57.

Built at Dundee. By whom Dundee S.B. Co. Ltd. When YEAR. 1908. MONTH. 1.

Owners Aberdeen Line Co. Ltd. Port belonging to Aberdeen.

Owners' Address (if not already recorded in Appendix to Register Book).

Surveyed ~~Afloat or~~ in Dry Dock? Yes. Name of Dock Lewis's Slip. Destined Voyage Coasting.

WB=CellDBorDBa ... feet; uE&B ... feet; f ... feet; total capacity ... tons. FPT ... tons; APT ... tons; MT ... feet ... tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 12811 Port Abn

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
CONT. 7. A.1. from 19.	ABN.	✠ L.M.C. 10.19.
+ 10.21.		T.S. 10.19. C.L.
For Coasting purposes		B.S. 10.21.

Society's Freeboard (if assigned) as painted on Ship and now verified ... ft. ... ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

Vessel placed on Pontoon. Bottom, keel & rudder cleaned, examined & recoated.

NOW DONE:- Seams and butts of bottom planking caulked and payed where necessary. Several new bolts fitted in bilge keels and rubbing blocks.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Deck	Good	State if Tanks have been examined inside	✓
Caulking of Decks	"	State if Tanks now tested	✓
Waterways	"	Bulkheads	✓
Coamings	"	Ceiling	✓
Beams & Fastenings	✓	Cement on ~~Asphalt~~ (State which.)	Good
Outside Plating	✓	Rudder	"
Caulking of ditto	✓	Steering gear and its connections	"
Rivets	✓	Windlass	"
Breasthooks & Crutches	✓	Have Pumps now been examined and found efficient?	Yes.
Transoms	✓	Have Sluice Valves now been examined and found efficient?	✓
Frames	✓	Have Watertight Doors now been examined and found efficient?	✓
Reverse Frames	✓	Have Ventilators and their Coamings been examined and found efficient?	Yes.
Floors	✓		
Keelsons	✓		
Stringers	✓		
Inner Bottom Plating	✓		

Dblng. Plates under Sounding Pipes	✓	Copper, or Y.M. of Wood Vessels (State if on Felt.)	✓
Engine Room Skylights	Good	When put on, Month ✓ Year	✓
Coal Bunkers, Open'gs, Lids, &c.	"	Boats	Good
Scuppers	"	Masts, ~~Yards~~, &c.	"
Cargo Hatchways	"	Condition, how ascertained	from deck
Hatches	"	(State if wedges removed)	no.
Planking of Wood Vessels	"	Sails	✓
Caulking ditto	"	Equipment letter	C.
Treenails ditto	✓	Anchors, No. of	2B. 1S. 1K.
Breasthooks & Stemson ditto	✓	Cables (State if now ranged)	no.
Transoms, Pointers, & Crutches ditto	✓	,, length ✓ size	✓
Timbers of Frame at openings ditto	✓	,, Rule length (on board) ✓ size	✓
Ditto ditto at other places ditto	✓	Hawser & Warps	Good
Stringers, Clamps & Shelfs ditto	✓	Standing & Running Rigging	"
Salting (State if examined.) ditto	✓		

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so, to be sent to

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of *ss No.* 1-15 and ptND15, &c."

This vessel appears to be now in good and efficient condition & in my opinion is eligible to remain as classed and to have record of Survey 10.22.

Wrecked 2,23

	£	:	:
Survey Fee (per Section 28)			
Special Damage or Repair Fee (if any) (per Sec. 29)		✓	
Travelling Expenses (if chargeable)			
Second Surveyor's Fee (if any)			

Fees applied for, ... 19 ... Received by me, ... 19 ...

D. Richardson

Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. OCT. 20 1922

Character Assigned Cont. 7 A1

For Coasting purposes

B.S. 10.22.

(The Surveyors are requested not to write on or below the space for Committee's Minute.) 10m.2.23.—Transfer Ink.

© 2020 Lloyd's Register Foundation