Do. of R. Qr. Dk. ..... Deduct height of 'tween deck when this does not exceed 8ft. 8.0 Built at Walker-on-

Do. of Bridge House ..... Transverse Number ..... 79.33 When built 1917 Launched

Do of Forecastle .....

250.1.14. WRECK BOX No 16 Bottom Wreck 16 Wreck 58 **F.E.**

Received by Chief Ship Surveyor 17.12.17 Received from Chief Ship Surveyor

VESSEL'S NAME Steel ⅌ "Garthwaite" Rpt. Nwc No. 70513

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Transverse No. 79.33 Depth "d" 22.98

Framing: Table No. 3 page 16 Description Bulb angles

Longitudinal No. 31732

Proportions $\frac{\text{Length}}{\text{Depth}}$ = 11.24

Deck Sheerstrake as approved.

Cargo battens are not fitted in the shelter 'tween decks.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A1 (Steel) Shelter deck with freeboard," as recommended. The Summer freeboard of 10' 2½" from centre of disc to top of statutory deck line at Shelter deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

✠ 100 A1 (Steel) Shelter deck with freeboard.
1 Dk (Steel) & Shelter deck (Steel)
Cell DB 361' 1160t. FPT 102t. APT 136t.
FK. 6BH. Cem. Lloyds A+CP.
in Shelter 'tween decks.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

MC. 17.12.17

It is considered the size of the upper deck beams & the equipment of stanchions & warps are as required by the rules also that the spacing of the knees in the bilges of 6 strake is as required but the Surveyor should be requested to state if this is so. The Surveyor should be requested to forward the usual longitudinal report.

© 2020 Lloyd's Register Foundation

BEAMS, Second, Third & Fourth Deck, ~~Single~~ Angle, Bulb Angle, Plate, Tee Bulb or Channel

,, Angles on upper edge .....

,, Spacing .....

,, Deck. Material and thickness

Poop Deck Stringer Plate, breadth & thickness

,, Angles on ditto .....