22 FEB 1963

Ship's name "ORIENTAL QUEEN" Port Yka. No4487

Last survey date 6.12.62.

GB Class is subject to set in shell plates J.6 & 7, K.6 & 7 (s.s. from fwd) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before xxxxxxx)

Surveys due C.S.H. (D) case - due date 9,64.

Nature of present survey (afloat and in drydock)

Docking: Damage repairs (various causes) and to the deferred items as above: Drilling of shell anddeck plating the reported results of which are considered satisfactory. Advancement of SS.

Is interim certificate in order Yes/~~No/None~~

~~Items outstanding if any~~

FOR PORTION OF SURVEY HELD:- See List in Ship Reports Dept.

SS proposed to be completed by

Recommendation

SUBMITTED record of 'DS 10,62' be assigned but without special conditions.

DS 10,62 Without.

IN S.R.L. APPENDIX.
Shell plate in 1st strake below sheerstrake between frs.39/40 (p.s.) slightly indented.
After centreline sheerstrake plate indented.
(C.S.H.)
Special Survey due 9,64 to be (D) Survey.

SPR. 6/2/63

NOTE:- Ship to be assigned 'DR' notation of 10,62 on completion of C.S.H. Survey.

X

Eng. S.2

© 2018