Rpt. 8

REPORT OF **SHIP SURVEYS AND REPAIRS**

Received London

WRECK SECTION

Ship's Name SS/~~MV~~ "ARISTON" Gross tons 1077

Is there a rpt. 9? No Port Copenhagen Rpt. No. 20385

No. of visits One First date and Last date 14.3.63

Interim Cert. issued & copy herewith? No Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only)

Date of completing rpt. 19.6.63 Surveyed at, if different from Port above Stubbekøbing

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D.

Has a Load Line Survey been held? No Freeboard Marks verified

State which additional Rpt. 8 is attached: ~~(Cont); (PS); (DR); (EQ); (Rig)~~

26 JUN 1963

Survey fees	Damage fee	Expenses
.	kr. 275,-	kr. 141,-
		S.A. fee

I have surveyed the above ship in accordance with the Rules for Damage stated caused by fire which occurred on 9.3.63 whilst vessel fast in ice off Stubbekøbing.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Found after accommodation entirely gutted, decks, casings and shell plating abreast boiler (PS) severely buckled.

Boiler room severely damaged including O.F. bunker bulkheads, all electric wiring, O.F. and fan units, generator etc.,

We are advised that it was subsequently decided by Owners and underwriters that, as the estimated cost of repairs was beyond the C.T.L. value, the vessel be disposed of for scrapping. The ship is now lying at Madenesund, Denmark.

~~Xxxx

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					

© 2018
Lloyd's Register Foundation