Do. of excess of Hatchways	45·47
Do. above Crown of Engine Room	84·05
Gross Tonnage	1154·74
Less Crew Space	53·78
Less above Crown of Engine Room	84·05

Girth of Half Midship Frame (as per Rule) ..... 31·00

1st Number ..... 64·54

Length on deck from after part of stem to fore part of stern post ..... 230·7

When built

By whom built Mackie & S

Owners J. Le. Boulanger

Managers

(1600-4-68.)

1

Chief Surveyors 23. 6. 03 Received from Chief Surveyors

EL'S NAME Stt. S.S. "Yukon" Report Gl. No. 20915

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, (24/5/92.)

e of Survey First entry ~~When due~~

+ 100 A1 ("Steel")

1 DR (Stt) + deep framing. Well Deck.

W. B = Cell DB a 73' a E 17' f 100' 367t FPT 43t APT 44t

FK 48H Cem. Lloyd's A+CP P18' Q67' B56' F23'

C.A.J. 23/6/03

" Quarter, 'tween Dks., " "									
" " in Hold " "	4" dia. spaced as per profile								
WEB FRAMES, In Fore Body, No. and Spacing	five				five				
" " " Brdth. & Thickness		18½	8			18½	8		
" No. of Side Stringers " "	See Bilge & Side Stringers								
WEB FRAMES, In E. & B. Space, No. & Spacing	one								

" Angle on ditto ..... → 3 × 3 6

" ~~Tie Plates~~ .....

" Deck, Material and thickness Steel

* If Iron or Steel Deck, state if whole or part, and if wood deck s

BULKHEADS.	Number. In Vessel.	Number. Per Rule.	Thickness.	STIFFENERS. Horizontal. Size.	Horizontal. Spacing	Vertical. Size.	Vertical. Sp
			~~16ths or~~ 20ths.	Inches.	Inches.	Inches.	In

© 2020 Lloyd's Register Foundation

C0201 3-C02023-0184