THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

002165- 002173-0177

SLD 30449.
GRK. 19197

LONGWOOD.

It is submitted that this vessel is eligible for THE RECORD.

+ LMC 8.30.

Oil Engines 4 S.C. 5A.
Reg. 24 4/16 - 51 3/16.
208. 150 A CL.

It is conducted that the lubricating oil pumps & their connections are fitted in accordance with the Rules but the Sunderland Surveyors should confirm this and state the number and size of these pumps & particulars of the spare pump. They should also confirm that the tenacity of the Boiler shell plates & strips ~~[illegible]~~ is 29/33 tons not 28/32 tons as reported. J.C. 1/9/30.

5/9/30

What pipes pass through the deep tanks None Have they been tested as per Rule —

Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times Yes.

© 2020 Lloyd's Register Foundation