Rpt. C. 11 (Contd.)

Index No. 22971
(For London Office use)

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name ABERSEA Official No. 131539

Port of Registry Sydney N.S.W.

This ship has been under survey at

on 195 and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~ :—

NEW HATCH BEAMS FITTED TO No. 1 HATCH (FREEBOARD DECK) AND TO No. 2 HATCH (RAISED QUARTER DECK)

All beams same scantlings 7 in Number at No. 1 Hatch.
6 " " " No 2 " .

Depth of beam over face plates = 14"
Thickness of webs = 7/16"
Face plates 8" x 5/8" top and bottom.
Spacing 4'-5/8"
Bearing surface 3 5/8"

New covers of Oregon Pine 2 1/2" thick, fitted fore and aft.
Bearing surface 3 1/2" min.
Steel galvanised end bands fitted.

Extracted from plan approved by Sydney N.S.W. Surveyors (22-8-56) forwarded to London 17/9/56.

JmB
2-10-56.

A copy of this Report has been placed on board.

5m,6,55. T.

© 2020 Lloyd's Register Foundation

002362-002373-0044