(Received at London Office TUES. 17 OCT 1905) No. 23166

# REPORT of SURVEY for REPAIRS, &c.

26 SEP 1905

...f writing Report 26 Sept 05 19 When handed in at Local Office 26 SEP 1905 19 Port of Glasgow

...in ...ook. Survey held at Glasgow Date, First Survey 21st Sept Last Survey 9th Oct 1905 (No. of Visits 2)

...lement on the ~~Wood, Iron or~~ Steel S. S. "AFRICA" Master

TONNAGE:— ...OSS 454 ...DER DK. 302 ...T 162

Built at Mary port By whom W. Walker When 1905 (YEAR. MONTH.)

Owners Adm S. S. Co Ld (E. J. Orbit Mgrs) Port belonging to London

Owners' Address (If not already recorded in Appendix to Register Book.)

...rveyed Afloat ~~or in Dry Dock?~~ ~~Afloat~~ on slipway Name of Dock Queens Destined Voyage

...B=CellDBorDBa ... feet; uE&B ... feet; f ... feet; ...al capacity ... tons. FPT ... tons; APT ... tons; MT ... feet ... tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides ...he tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ...ters, and of the inner bottom plating, especially in the boiler space.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

| CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys. | Years Assigned or expired. | Machinery and Boiler Surveys (including date of N.B., if any). |
|---|---|---|
| 100 A.1. | | |
| Class Continuous | | |

...ast Report, No. ... Port ...

...riodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the ...use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs ...account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; ...d besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the ...placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on ...e back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified ... ft. ... ins.

...damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were ...declined? ... also whether any damage report was made, and, if so, by whom? ...

~~...PAIRS, OR~~ EXAMINATION AS PER RULE, FOR Classification

The hedge anchor for this vessel has now been put on board & Engine & Boiler casing rivetted up in a satisfactory manner.

This vessel has been placed on Kelvinhaugh slipway & the bottom & rudder have been cleaned & revalted.

| ...MMARY OF DAMAGE REPAIRS :— | Plates. | Frames. | R. Frames. | Floors. | Beams. | Str. Plates. | Dk. Plates. | Other Items :— |
|---|---|---|---|---|---|---|---|---|
| Renewed ... ... ... ... ... ... ... | | | | | | | | |
| Removed and Faired or Repaired ... ... | | | | | | | | |
| Faired or Repaired in place ... ... ... | | | | | | | | |

...ESENT CONDITION OF THE

...ks ...
...alking of Decks ...
...terways ...
...amings ...
...ams & Fastenings ...
...tside Plating ...
...alking of ditto ...
...rets ...
...easthooks & Crutches ...
...ansoms ...
...ames ...
...verse Frames ...
...oors ...
...elsons ...

Stringers ...
Inner Bottom Plating ...
State if Tanks have been examined inside ...
State if Tanks now tested ...
Bulkheads ...
Ceiling ...
Cement or Asphalt ... (State which.)
Rudder ...
Windlass ...
Have Pumps now been examined and found efficient? ...
Have Sluice Valves now been examined and found efficient? ...
Have Watertight Doors now been examined and found efficient? ...

Dblng. Plates under Sounding Pipes ...
Engine Room Skylights ...
Coal Bunkers, Open'gs, Lids, &c. ...
Scuppers ...
Cargo Hatchways ...
Hatches ...
Planking of Wood Vessels ...
Caulking ditto ...
Treenails ditto ...
Breasthooks & Stemson ditto ...
Transoms, Pointers, & Crutches ditto ...
Timbers of Frame at openings ditto ...
Ditto ditto at other places ditto ...
Stringers, Clamps & Shelfs ditto ...
Salting ditto ... (State if examined.)

Copper, or Y.M. of Wood Vessels ... (State if on Felt.) When put on, Month ... Year ...
Boats ...
Masts, Yards, &c. ...
Condition, how ascertained ... (State if wedges removed)
Sails ...
Equipment letter ...
Anchors, No. of ...
Cables (State if new ranged) ...
" length ... size ... (on board)
" Rule length ... size ... (per Table 22)
Hawsers & Warps ...
Standing & Running Rigging ...

## General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of *ss No.* 1–98 and ptND98, &c.."

The above is for the information of the Committee

Office Fee (if chargeable) *per Scale II., Sec. 27* ....£ : :
Survey Fee *(per Section 28)* ....£ : :
Special Damage or Repair Fee (if any) *(per Sec. 28.)* ....£ : :
Travelling Expenses (if chargeable) ....£ : :
Second Surveyor's Fee (if any) ....£ : :

Fees applied for, ... 19 ...
Received by me, ... 19 ...

P H Mackillop
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Glasgow 16 OCT 1905

Character Assigned For the Committee's information.

TUES. 24 OCT 1905

If so to be sent to ... Certificate required?

© 2020 Lloyd's Register Foundation

002410-002417-0044