Lloyd's Register of Shipping.

2m.11.35.

1

Sent to Chief Surveyors _____ *Received from Chief Surveyors* _____

VESSEL'S NAME Single Sc. M.V. "SAINT EUNAN" *Report* Gls. *No.* 5912

For the CHIEF SHIP SURVEYOR ~~and CHIEF MARINE SURVEYOR~~.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey _____ *When due* _____

NOTED TRO S

✠100A1

1 Dk.

Cell.DBuE & a 32' 24t, FPT 50t, APT 17t.

FK, 3BH, cem., Lloyd's A & CP.

P 33', Q 56', F 21'.

Machy. aft

O.L. 144.25'

10.12.37

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.

© 2020 Lloyd's Register Foundation

003106-003711-0011