DOCKING

Fastenings

2E

Received from Chief Engineer Surveyor

ef Engineer Surveyor

ME "LOUIS LANTZ" REPORT Ham. No. 5152

LMC due 7,55 partly held as a C.S. now completed.

DBS due 9,55 partly held 8,55 now re-held.
xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx

Vessel in dry dock. Both screwshafts seen. Steam pipes tested.

Some repairs done and vessel converted to an ore carrier in accordance with approved plans.

Port screwshaft renewed.

IT IS SUBMITTED the vessel is eligible to remain as classed.

ORD of survey +LMC CS 10,56 DBS 9,56 sps 10,56 xxxxxxxxxxxxxx
port S.N (CL)8,56 starboard S. 8,56.

9.1.57.

© 2020 Lloyd's Register Foundation

FOR C.E.S. RECORDS TO NOTE

004055-004061-0004