Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Received London
19. NOV. 1965

Ship's Name SS/~~MS~~ "SANTA KYRIAKI"
No.L.R. 540861
Gross tons 2802 Port of Registry MONROVIA Port Lisbon

Date of build 10-1945 Is there a Rpt. 9? No Rpt. No. 11288

No. of visits One First date and Last date 23-10-65

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? Yes Last rpt. (H.Q. only) NWC 2113.

Date of completing rpt. 10-11-65 Surveyed at, if different from Port above -

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -

Has a Load Line Survey been held? No Summer freeboard as verified -

State which additional Rpt. 8 is attached: (~~Cont~~); (~~PS~~); (~~DR~~); (~~EQ~~); (~~Rig~~)

Survey fees - Damage fee Esc: 800$00 Expenses Esc: 60$00

16/11/65

S.A. fee -

23 NOV 1965

I have surveyed the above-named ship in accordance with the Rules for Damage

DAMAGE. Stated to have occurred whilst the vessel was entering Barry Docks on the 10th October 1965 at 19,04 hours and being due to high winds and currents causing the vessel to make contact with the quay wall on the port forward side.

FOUND Port side forward, second strake below sheer, third plate from forward and adjacent plates set in together with two frames.
No repairs carried out at this port.
Damage specially examined and shell plating being considered to remain efficient without repair until the next dry docking.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed ~~with~~/without fresh record of ~~dry-docking~~ survey. Subject to the port forward indent in second below sheer strake, third plate from forward being specially examined and dealt with as necessary at the next dry docking. Subject also to all other special conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

E. Hardcastle
E. Hardcastle
Surveyor to Lloyd's Register of Shipping

DF
ALSO FOR
SPL FOR
TRO
SRL
POSTING
HEADER
CERT

NOTED S.R. RECORDS DEPT.

Date of Committee MONDAY 29 NOV 1965

Minute As now, sub-cit

M.T.

FOR CHAIRMAN CLASSN. CTTEE

004369-004373-0263

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

(MADE AND PRINTED IN ENGLAND)

© 2020 Lloyd's Register Foundation