WS 22 SEC

F R. SECTION N°

No. 20854 in R.B.

Vessel's Name _Twin m. Tank_

Built at _Vegesack._ When

Owner's Name _Panama Trar. ton: Company_

Address _P.O. Drawer 2013, Balboa,_

when handed in at Local Office _June 11_ 19 _42_ Po

_New York_ Date, First Surve

Steel _Twin Sc m/r "C.O. Still_

at _Vegesack_ By whom _Ame_

Wreck Book ers _Panama Transport Co._ Owner

agers

Dry Dock? _Dg Dk._ Name of Dock _Bethl. Stee_

feet; uE&B sually noti _Brookly_

_Company_ feet

**Particulars of Class**

Case previously before Classing Committee. { Date

{ Last Minute

+100 A1    +LMC.
10.41.    DBS 3.41
SS.No 3 -8.40 -  TS 8.41
Carrying Petroleum in
oil Engine
2 WT DGS

Date of Casualty _About 10th June, 1942_

Précis of particulars of Casualty _Sunk by submarine off the United States Atlantic coast about the 10th June, 1942._

| | floors and Bracket Floors | Beams |
|---|---|---|
| | ✓ | ✓ |
| | ○ | ✓ |
| | ✓ | ✓ |

Engine Room
Coal Bunker
Oil Bunkers
Scuppers
Cargo Hatch
Hatches

Windlass

Have pumps been examined and found efficient?

Have Sluice Valves been examined and found efficient?

Have Watertight Doors been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

internally? _no_ Air and Sounding Pipes
_no_ Doubling Plates under Sounding Pipes

Planking
Caulking
Treenails
Breasthooks
Transoms,
Timbers o
Stringers
Salting
(State

servations, Opinion as to Class, Recommenda

ate clearly whether any and, if so, what alteration is suggested to be made in the existing cl
vey, thus, for example:—" to remain as classed in the Register Book
1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss

_Vessel is eligible, in my opinion, to u_

_8 of Survey 05-42_

Suggested Record

Date of Committ

ction 29)

r Repair Fee (if any) £

nses (if chargeable) £

yor's Fee (if any) £

Committee's mittee's Minute

Character Assigned _100 A1_

_Carrying Petroleum in bulk_

_D.B.S. 5.42_

Fees applied for
_June 11 1942_

Received by me,
19