2m.8.46. MW

...t to Chief Surveyors..... Received from Chief Surveyors..... 21 MAY 1947

...SSEL'S NAME EMPIRE HARLEQUIN REPORT..... No.....

**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.**

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(*Extract from Sub-Committee's Report*, 24/5/92.)

...re of Survey - When due -

This Tug was built in 10,43 and classed ✠100A1 "For Towing Services".

The Owners, Sudan Railways, state in a letter dated 9.4.47 that classification of this vessel by the Society will no longer be required.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawl of class at the Owners' request.

Withdraw Class

and insert (...)

JST 15.5.47. L.G.

© 2020 Lloyd's Register Foundation

006248-006257-0131