Less Crew Space 6. 64
Less above Crown of Engine Room ..... } stern post ..... Managers ..... Reg. Book).

F.E.

Received from Chief Ship Surveyor .....

y Chief Ship Surveyor 18. 1. 06

'S NAME Stt. Steam Trawler "Isle of Wight" Rpt. Hull No. 17457.

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	8/16" in lieu of 7/20"	Not required.
Spar Sheerstrake . .	✓	✓
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle).	Ordinary, 5/16" thick in lieu of 5/20" and spaced 1" closer than required.	

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A 1 ("Steel") "Steam Trawler" as recommended.

✠ 100 A 1 ("Steel") "Steam Trawler"
1DR.
W. B = DTf 13' 34t
BK 8" 4BH Cam. Lloyd's A & CP

C. H.
18/1/06

The Superintendent of the Netherton Proving House should be requested to state the dates when the anchors and chain cable were tested, and the name of the makers.

C. H.

© 2021 Lloyd's Register Foundation

006343-006357-0011

5c,5,5.

" " in Hold " "		✓					
WEB FRAMES. In Fore Body, No. and Spacing		✓					

" Tie Plates .....
" Deck, Material and thickness .....
* If Iron or Steel Deck, state if whole or part, and if w