No. 7563.

21346

REEBOARD VERIFICATION FORM FOR STEAMERS.

When received in London Office WED. 30 NOV 1910

...undee

...me S. S. "TINTO"

✓ 132215 No. in Reg. Book 30 in suppt.

...gistry (*For Foreign Vessels*) Hull

...el Steel State whether Classed by Lloyd's Register ⚓100 A.1. CONTEMPLATED.

...wners J. Wilson, Sons & Co. Ltd. Date of Verification 29th Nov. 1910

...have to report that the Freeboard from the centre of disc to the top of the ...ck line, and the lines in connection therewith, as given below, assigned ...mittee to this vessel, have been correctly marked on the vessel's sides, ...ce with the printed instructions:—

...tre of disc to top of statutory deck line	— ft.	10	ins. ✓
...tre of disc to top of statutory deck line ... awning or part-awning deck	ft.		ins.
...n water line above centre of disc . . .		3½	ins. ✓
...n Summer line above centre of disc . .		2	ins. ✓
...er line below centre of disc		2	ins. ✓
...er North Atlantic line below centre of disc		4	ins. ✓
...e between the top of statutory deck ...e on vessel's side and the intersec- ...n of the continuation of upper side of ...ed or iron deck with the vessel's side	at main, ~~spar or upper~~ dk.	1¼	ins. ✓
	~~at awning or pt.-awning dk.~~		ins.

...t should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

...to have machinery fitted on board in Hull, and to ... Survey for freeboard Casings & trunk to be riveted & number to obtain Matthew Blackwood Surveyor.

...d up in London Office.)

No. 21346 Date of Committee's Minute 29.11.10

...epth for record . . . . . 14 ft. 6 ✓ ins.

...compared and found correct by GKM date 30.11.10

...? new Vessel Form for Certificate A

~~Write Certificate & Post~~ [illegible] date 10.1.11

...written 10.1.11 Noted for posting [illegible]

©2020 Lloyd's Register Foundation

006723-006730-0215