ir,

IAME "ALASTOR" Report No. 00098.

TESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in 1/16 of an inch.

	AMIDSHIP.					FORWARD.					AFT.					REMARKS.
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
LAKE																4 plates p.&s. in the F-strake doubler amidships.
RAKE	10/11	9-	10	1-		9	9	9+			8	9	9.5			
	8	7-	7+	1+	1-	7	6+	6+	1-	1-	7	6+	6	1-	1	Holes at forward end differ
	9	9-	9-			8	6+	7+	2-	1-	8	7+	8	1-		in second frame space
	8	13-	13½			7	7-	7.5			7	7	6+		1-	abaft the collision bkhd
	9	7+	9	2-		8	8	7.5		½	8	7	8	1		
	8					7					7	6.5	6+	½	1-	At after end in the 11th frame space from stern.

T. Anderson.

Drillings at ends to be made in the vicinity of the peak bulkheads.

© 2021 Lloyd's Register Foundation

007783-007793-0326

W. E. Johnson