No. of ~~Aux.~~ Donkey Boilers 1 W.P. 100 lb. Hull + 100 A 1 with freeboard + LMC

COPY

LLOYD'S REGISTER OF SHIPPING

Port KIEL

23rd January, 1960

This is to Certify *that I have*

Surveyed the part Machinery of the "EDWARD DEMBOWSKI", 4750 tons gross of Gdynia as she lay afloat and in dry dock at Kiel on November 16th, 1959, and subsequently,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will **Recommend** *that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book* DBS 9.59 as previously recommended and CS (with date) when the survey has been completed,

and that her Machinery Classification Record be continued in the Book.

Parts now examined: Propeller, after end of Stern bush and outside fastenings.

(C.S. Items only)

Main Engine Nos. 1, 2, 3, and 6 cylinders, covers, pistons, rods valves and gears, connecting rods, top ends and guides, crankpins and bearings.

Main Engine Nos. 1, 2, 3, and 4 main bearings, and journals.

Port aft.outer auxiliary engine in its entirety with attached air air compressor. (Intercoolers and oil cooler tested).

(J.H.Harbottle) *Engineer Surveyor to Lloyd's Register.*

P.T.O.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2021 Lloyd's Register Foundation

(Cert. B.I.) 100m,4,57 (MADE AND PRINTED IN ENGLAND)

008823 - 008830 - 0120

Rpt. 6 (Ship & Eng.) 100m,11,57. (MADE AND PRINTED IN ENGLAND)

(TURN UP