5c8,11.

F.E.

Received by Chief Ship Surveyor 21/11/11 *Received from Chief Ship Surveyor*

VESSEL'S NAME H.M.S. "Aquamarine" Rpt. Hull No. 24411

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Transverse No. 37.375 Depth "d" 12.00

Framing: Table No. 3 page 9 Description Single angle, as approved

Longitudinal No. 5232

Proportions $\frac{\text{Length}}{\text{Depth}}$ = 10.37

~~Deck~~ Sheerstrake .62 in lieu of .38

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A-1. ("Hull") "Steam Trawler", as recommended

✠ 100 A-1. ("Hull") "Steam Trawler"

BK 8" 4 BH. 1 Dr. Cem. Lloyds Ar 60 Q 75 F 22

RBM 21/11/11

© 2021 Lloyd's Register Foundation

004321-004330-0115

,, Spacing		✓					
BEAMS, Third and Fourth Deck, Single Angle,		✓					

Poop Deck Stringer Plate, breadth & thickness

,, Angle on ditto