Less Crew Space 75·19

Length on deck from after part of stem to fore part of stern post ..... 313·2 | 313·2

Owners NAVIGAZIONE LIB

3m,1,7.

1

Sent to Chief Surveyors 31/12/07

Received from Chief Surveyors

VESSEL'S NAME Stt SS "Luna"

Report Guk No. 15290

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in conection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey First entry

When due

+ 100A·1 ("Steel")

1 Dk (pt Inc - pt Stl) & deep framing

NB = Cell D. Ba 106 n E 18 f 134 703t A.P.T 54t

F.K. 5 B.H. Cem. Lloyds A & C.P. P37 B94 F31

RBW

31/12/07

C.H.J.

© 2021 Lloyd's Register Foundation

009362-009375-0185

" " Hold " " CENTRE LINE BULKHD; SEE UNDER BULKHDS.

" ~~Quarter, 'tween Dks.,~~ " "

Forecastle Deck Stringer Plate, Bulth & thickness

" Angle on ditto 4