15 MAR 1929

(Received at London Office [redacted] 1929) No. 39691.

EPORT of SURVEY for REPAIRS, &c.

14 MAR 1929 — 14 MAR 1929

...writing Report ..... 19.... When handed in at Local Office ..... 19.... Port of HULL.

Survey held at Hull Date, First Survey 5th March Last Survey 13 March 1929.
(No. of Visits 8.)

...ok. ...83 on the ~~Wood, Iron or~~ Steel s/s "Cilurnum"

			YEAR.	MONTH.
...ONNAGE:— ...S 3077 ...ER DK. 2844 ... 1848	Built at Middlesbro'	By whom Sir Raylton Dixon & Co Ltd	When 1919	
	Owners Antonio Menchaca	Owners' Address (if not already recorded in Appendix to Register Book).	Bilbao	
	Managers	Port belonging to	Bilbao	

...eyed Afloat or in Dry Dock? both. Name of Dock Alexandra Destined Voyage

...=CellDBorDBa ..... feet; uE&B ..... feet; f ..... feet
...l capacity ..... tons. FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, , and of the inner bottom plating, especially in the boiler space.

...st Report, No. ..... Port .....

...odical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the ...e of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs ...account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the ...acement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on ...back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years assigned and how expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A1 (condemplated)		

...mage cases where the Surveyor has not made a special damage report he is required to state whether he ...ffered his services for this purpose and to whom and why they were declined .....

Society's Freeboard (if assigned) as painted on Ship and now verified 4 ft. 1½ ins.

Was a damage report made by anyone else? If so, by whom?

...AIRS, OR EXAMINATION AS PER RULE, FOR Classification & S.S. No 3.

...ow done:- Vessel placed on high blocks in dry dock. Bottom & Rudder cleaned, examined & recoated. The Holds, Peak & Lower Bunkers cleared & examined, ceiling & sparring all lifted; The Chain Lockers cleared & examined. Anchors & Cables ranged & examined. Bilge ...ounding pipes examined, heating in way of sidelights examined. ...ll Double Bottom & Fore & aft Peak Tanks tested to rule requirements found tight. The Fore & Aft Peak Tanks examined internally The 2'dle & Poop Decks examined. Hatch coamings, covers supports & ...ropaulins examined, Shell testing (see F.E. Rpt.). Freeboard marks cut in ...vessels sides & verified.

P.T.O.

...MMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

...ESENT CONDITION OF THE

...ks part exd good
...lking of Decks ... "
...mings ... "
...ms & Fastenings ... "
...side Plating ... "
...asthooks ... "
...nsoms ... "
...mes part exd. "
...verse Frames ... ✓
...ngitudinals ... ✓
...ansverses ... ✓
...oors part exd good
...elsons ... "
...ringers ... "
...er Bottom Plating ... "

State if Tanks have been examined inside Tanks
State if Tanks now tested yes
Bulkheads good
Ceiling "
Cement ~~or Asphalt~~ (State which.) part exd good
Rudder "
Steering gear and its connections "
Windlass "
Have Pumps now been examined and found efficient? not exd
Have Sluice Valves now been examined and found efficient? —
Have Watertight Doors now been examined and found efficient? not exd.
Have Ventilators and their Coamings been examined and found efficient? yes

Dblng. Plates under Sounding Pipes ~~part exd~~ good
Engine Room Skylights "
Coal Bunkers, Open'gs, Lids, &c. ~~part exd~~ "
Scuppers "
Cargo Hatchways "
Hatches "
Planking of Wood Vessels
Caulking ditto
Treenails ditto
Breasthooks & Stemson ditto
Transoms, Pointers, & Crutches ditto
Timbers of Frame at openings ditto
Ditto ditto at other places ditto
Stringers, Clamps & Shelfs ditto
Salting (State if examined.) ditto

Copper, or Y.M. of Wood Vessels ✓ (State if on Felt).
When put on, Month ..... Year —
Boats good
Masts, ~~Yards, &c.~~ "
Condition, how ascertained from ak (State if wedges removed) —
Sails —
Equipment letter U
Anchors, No. of 3.1
Cables (State if now ranged) yes
" length 270 fms (on board) size 1⅞
" Rule length " " size 1 15/16.
Hawser & Warps sufficient
Standing and Running Rigging good

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of *ss No.* 1–24 and ptND24, &c."

This vessel, so far as now seen is in good & efficient condition, eligible in our opinion to be classed 100 A1 with the Notation of S.S. Hull No 3. 3.29 when the Classification and special survey requirements are satisfactorily completed

...urvey Fee (per Section 29) £ 50 : 0 : 0
...pecial Damage or Repair Fee (if any) (per Sec. 29) £ : :
...ravelling Expenses (if chargeable) £ 1 : 1 : 0. Late attendance Section Ltr No. 13.3.29.
...econd Surveyor's Fee (if any) £ : :

Fees applied for, ... 19....
Received by me, 16.7 1929 HUG

AMR

John Needham
John Mackirdy
Surveyor to Lloyd's Register of Shipping.

Is Certificate required? If so, to be sent to

010720-010726-0711

...ommittee's Minute TUE. 2 JUL 1929

...haracter Assigned see Minute on Bbo Rpt 75-25

© 2021 Lloyd's Register Foundation

To Complete this survey:- All Double Bottom Tanks to be examined internally. The Upper Deck fore & aft & Bridge Decks to examine. The Machinery space to examine The Windlass, Steering Gear, Masts & Rigging. W. T. doors. pumps & general equipment to examine
The remaining requirements for the F. & Report herewith to be completed.

Wear & Tear Repairs
The Rudder lifted, pieces fitted. 3 Pintles renewed, 2 skimmed up. 4 bushes renewed
Local doubling fitted over fractured shell plate on P. side of No. 1 B'hd (Bracket
Keel plate overlap (forward) refastened with buttstrap. Bilge keel riveting
part renewed. A few started rivets in C L Bulkhead renewed
10 Stiffeners on H.P. B'hd (bot. part) reinforced with new bars.
Sounding plates made good in bilges. Suction Pipes at Bulk Hds.
overhauled

The Supt states vessel proceeds from this Port to Bona thence to Bilbao where the survey will be completed within the next three months.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificate.	Anchors.*	Weight, Ex. Stock. Cwts.	qrs.	lbs.	Weight of Stock. Cwts.	qrs.	lbs.	Test, per Certificate. Tons.	Cwts.	qrs.	lbs.	Weight Required by Rule. Cwts.	qrs.	lbs.	Description of Anchor.	Makers.	Where and when tested and Superintendent.
	1st Bower ...														If Patent state name of Patentee.		
	2nd "																
	3rd "																
	Collective Weight.																
	Stream																
	Kedge.....																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Number of Certificate.	Length and size supplied. Length. Fathoms.	Diam. Ins.	Test per Certificate. Statutory. Tons.	Breaking. Tons.	Weight of Chain Cable. Supplied. Cwts. qrs. lbs.	Per Rule. Cwts. qrs. lbs.	Length and size per Rule. Length. Fathoms.	Diam. Ins.	Description.	Makers of Cables.	When and where tested and Superintendent.
Iron Stream Chain or Steel Wire....											

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

© 2021 Lloyd's Register Foundation