FORECASTLES HAVING LONG POOPS, OR RAISED QUARTER DECKS DISCONNECTED, OR CONNECTED WITH BRIDGE HOUSES, OR OTHERWISE.

Ship's Name.	Port of Registry and Nationality.	Official Number.	Gross Tonnage.	Date of Build.
INGRID THORDEN. KNAPPINGSBORG				

COPY

Lloyd's Register of Shipping.

Port LONDON.

17th October, 1932.

This is to Certify that

THOMAS E. SOWDEN,

undersigned Surveyor to this Society did at the request of Owners of the Steel Screw Steamer "INGRID THORDEN", 1885 tons ss, of Kungsbacka, whilst the vessel was lying in the Surrey ks, London, on the 17th October, 1932, verify the freeboards ked on the ship's sides in accordance with the International dline Convention, 1930, and survey the alterations required in nexion therewith.

The requirements of the Swedish Government for existing ships been complied with.

nary Cargo.

board amidships from top of deck line Steel Deck.		From centre of disc.
pical Fresh Water.	267 mm.	255 mm.
h Water.	387 mm.	135 mm.
pical.	402 mm.	120 mm.
er.	522 mm.	
er.	642 mm.	120 mm.
er North Atlantic.	693 mm.	171 mm.

er Deck Cargo.

board amidships from top of deck line Steel Deck.		
ical Fresh Water Timber.	146 mm.	376 mm.
h Water Timber.	268 mm.	254 mm.
ical Timber.	284 mm.	238 mm.
er Timber.	406 mm.	116 mm.
er Timber.	569 mm.	47 mm.
er North Atlantic Timber.	693 mm.	171 mm.

Surveyor to Lloyd's Register of Shipping.

is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
mmittee use their best endeavours to ensure that the functions of the Society are properly executed, it is t neither the Committee nor the Society are under any circumstances whatever to be held responsible for y report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other ociety, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents

010835-010845-0206

19.10.2

Winter Line below " " " ... ...

Winter North Atlantic Line " " " ... ...

king, or ceiling are of unusual thickness the breadth of vessel to inside reported if possible.

Lloyd's Register Foundation