Rpt. 8   REPORT OF **SHIP SURVEYS AND REPAIRS**

RB 91496   Received London

Ship's Name SS/MS   CASWELL   Gross tons 276

Is there a rpt. 9?   Port   ON A   Rpt. No. 164635

No. of visits   First date   Last date

Interim Cert. issued & copy herewith?   Damage rpt. issued & copy herewith?   Last rpt. (H.Q. only) 15/7/65 kw

Date of completing rpt.   Surveyed at, if different from Port above

Surveyed afloat and/or in D.D.   Last date of examination in D.D.

Has a Load Line Survey been held?   Freeboard Marks verified

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees   Damage fee   Expenses

S.A. fee

I have surveyed the above ship in accordance with the Rules for

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

I recommend that this ship remain as classed with/without fresh record of dry docking

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Surveyor to Lloyd's Register of Shipping

Date of Committee   FRIDAY 26 OCT 1962

Minute   Owners request.

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

011161 - 011170 - 0101

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new. Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or welded in place					