COPY.

LLOYD'S REGISTER OF SHIPPING

RPT.No.35257

Port ....BUENOS AIRES......

25th.June, 1963

This is to Certify *that I have*

surveyed the M.Tanker "SAN ANTONIO" 11163 *Gross tons* of Buenos Aires whilst afloat and in Drydock at Bahía Blanca on the 24th.October 1962 & subsequently on account of Re-classification and Wear & Tear Repairs.-

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be re-instated in her former Class in the Register Book, VIZ '- +100 A1 Carrying Petroleum in bulk; longitudinal framing at bottom and at deck, Part electrically welded, and to have record of drydocking 5,63 and the Notation S.S. 6,63 (Dr.), Subject to 240 fathoms of chain cable being renewed at the first opportunity.

J.Moar for A.F.Sinclair

Surveyor to Lloyd's Register of Shipping

& E.H.Holmes-Brown (Acting surveyor to Lloyd's
Register of Shipping)

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	CSH	Hull Special Survey (Continuous)

Cert. B