"TIO PEPE"

This ship was built in 1949 and then classed 100A-.

After being sunk due to collision with another ship the class was withdrawn and the Notation "Sunk by collision 2,52" inserted in the Register Book 9,52.

The ship has now been salvaged and in a letter dated 17.10.53 the Cadiz Surveyor states that the Owners request Reclassification.

IT IS SUBMITTED the CADIZ Surveyor be informed that in order that this ship may have her class 100A1 inserted in the Register Book, the following will be necessary:-

1. the requirements of a SPECIAL SURVEY (C) to be complied with, including the drilling of the structure, if necessary, where signs of wastage are evident.

2. If any structural alterations are now required which affect the longitudinal or transverse strength of the ship, plans should be submitted for approval, and

3. full particulars of the equipment on board, including weights, tests, etc. of anchors and tests, etc. of chain cable to be furnished.

R.S.B

27.10.53.

? No Engineering Sheet

© 2021 Lloyd's Register Foundation

011610-011618-0148