710mm dia. (All Oil T. hatches).

No. .... Place Aioi Hyogo-Ken Japan   Date   21 Jan. .... 1955 ...

We   request   that   the   Committee   of   Lloyd's   Register   will   instruct   the Society's   Surveyors   to   Specially   Survey   during   Construction   the   Hull,   Engines   and Boilers   of   the   Vessel   No. 495 .... building   by   Messrs. Harima Shpbuilding & Eng. Co., Ltd. .... for Messrs. Daikyo Petroleum Oil Co., Ltd. of 21100 DW Tons. Length 167m ....., Breadth 22.3m ....., Depth 12.3m intended   to   be   Classed ✠ 100A1 "Carrying Petroleum is bulk" ✠ LMC.

We   undertake   to   arrange   for   every   facility   to   be   given   to   the   Surveyors to   carry   out   the   duty   in   question,   and   we   agree   to   pay   the   fees   for   the   Surveyor's services,   in   addition   to   the   actual   travelling   and   other   expenses   incurred   by   the Surveyors   in   connection   therewith.

This   request   is   made   upon   the   terms   of   the   Rules   and   Regulations   of Lloyd's   Register   of   Shipping,   which   provide   that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Engine Makers Isikawazima Heavy Industry K.K.

Boiler Makers The Harima Shipbuilding & Engineering
                          Co., Ltd.
Signature   K. Sugita

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—
"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

011619-011627-0083

The amount of Entry Fee. Scale £848600   Fees applied for,   (Special notations where