For the information of Surveyors and the Committee only.

Received at ..... Office 19

Lloyd's Register of Shipping.

m: 16910/St
st : 2039/748
et : 3365
. 1687

(Report on Vessel No. 7409 Port TRIESTE)

SHIP ~~FORGINGS OR~~ CASTINGS.

I have to report that the undermentioned ~~Steel Forgings or~~ Castings, manufactured by Mess. Witkowitz Bergb & Eisenh Gewerk
f Witkowitz *for the Vessel No.* 749 *, being built*
y Stabilimento Tecnico Triestino *of* Trieste
ave been inspected by me as set forth below and found to be, so far as can seen, Two Propeller Brackets, sound and free from defects,

rgings or ~~Castings~~

loyd's
.1687
20.1.26 61/62

VIENNA 21st January 1926

Albert Davi
Surveyor

	Propeller Bracket ~~Sternframe~~	Propeller Bracket ~~Rudderframe~~	STEM.
... ...	Siem. Martin Steel	Siem Martin Steel	
... ...	Cast Annealed	Cast Annealed	
... ...	To Sketch	To Sketch	
Inspection ...	Finished	Finished	
Inspected	2.12 to 20.1.26	2.12.to 20.1.26	
TINGS. tandard Test eces.	No: 61	No: 62.	
— uare inch ...	27.1 27.2	32.1 32.8	
er cent. ... 3"	32.1 43.4	32.1 26.4	
g Test— 80m/m	31.8 42.9	31.9 26.0	
fracture ...	120 degrees good	120 degrees good	
ground	Dispensed with	Dispensed with	
Test— ording to Rules satisfactory ...	Satisfactory	Satisfactory	

~~PROPELLER BRACKETS STERNFRAMES RUDDERFRAMES RUDDERSTOCKS PINTLES AND GUDGEONS~~ s.

any chargeable) £ : :

e paid at Vienna

, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

ate if annealed

© 2021 Lloyd's Register Foundation