COPY

LLOYD'S REGISTER OF SHIPPING

5660

Port DJAKARTA

9th October 1959

This is to Certify *that I have Surveyed the* DONKEY *Boiler and Machinery of the* m.v. "TANDJUNG TORAWITAN", 1712 Tons Gross of Djakarta, on the 13 April 1959 and subsequently, whilst in dry-dock and afloat at Tandjong Priok

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have Recommended *that the record of* Classed + LMC 10,59; TS(CL) 8,59 and ES 10,59

be made in the Register Book in the case of this vessel ~~*when the survey has been completed.*~~ subject to the Donkey Boiler not being used until Surveyed and its safety valves adjusted.

~~Parts now examined :-~~

NOTE:- Main Engine not to be operated continuously below 90 engine RPM with either the working or spare propeller fitted.

NOTE:- Main Engine "A" brackets repaired in way of telescopic pipe brackets at Nos6,8 and 9 main bearings.

(J.A.Boater). J. A. Boater. *Engineer Surveyor to Lloyd's Register*

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.1. (C.S). 80m,1,57. (MADE AND PRINTED IN ENGLAND.)

013008-013017-0047

Lloyd's Register Foundation