F.E.

Received by Chief Ship Surveyor 21. 11. 07 *Received from Chief Ship Surveyor*

VESSEL'S NAME Stt. S.S. Fishing Vessel "Provider" Rpt. Apl. No. 2895

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	1/20"	not required
Spar Sheerstrake . .	✓	✓
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle).	Ordinary, increased to compensate for omission of reverse frames.	

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A 1 ("Steel") "For Fishing purposes" as recommended.

✠ 100 A 1 ("Steel") "For Fishing purposes".
1 DR.

W. B = FPT 10t

BK 6" 4 BH Cem. Lloyd's A+CP

C.A.
21/11/07

© 2019 Lloyd's Register Foundation

BID77-0562

Plate or Tee Bulb .....
Angles on upper edge .....
Average space .....
LABS. In tween Deck size and ...

Bridge Deck Stringer Plate, br'dth & thickness
" Angle on ditto