S.S. "Bayelgette"

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office)

LLOYD'S REGISTER OF SHIPPING RECEIVED 20 NOV. 86 LONDON

No. 4024

TESTS OF BOILER STEEL.

Tests of 4 Steel Plate manufactured by Messrs D. Colville & Sons of Motherwell

for Boiler No. 152.Z. to be constructed by Messrs The Barrow Shipbuilding Co of Barrow-in-Furness

for .....

Date first visit Nov. 5th 1886 last visit ..... No. of visits .....

The ..... specified in the accompanying copy of Advice Notes were rolled from ..... charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a shearing from each plate

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions. Thickn. Ins.	Brdth. Ins.	Area. Ins.	Ultimate Stress. Total. Tons.	Sq. Inch. Tons.	Exten. in 8 ins. %	Remarks.
1	6.2 Rod. x 54 x 25/32	B853		1208	.80	21	1.736	49.20	28.3	26.5	

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

Fee ..... £ : :

Expenses £ : :

£ : :

To be paid by .....

H. M. Dove

Surveyor, Lloyd's Register,

Glasgow

17-11-86

21/11/86

[T. & Son—6000 —5/5/85.]

© 2021 Lloyd's Register Foundation