No. .....

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office, 5 MAY 85)

LLOYD'S REGISTER OF SHIPPING RECEIVED 5 MAY 85 LONDON

TESTS OF BOILER STEEL.

Tests of 12 Steel straps manufactured by Messrs. D. Colville & Sons of Dalzell, Motherwell

for Boiler No. 103 to be constructed by Messrs. Shanks & Co. of Dundee

for S.S. No. ~~21~~ 23 building by Messrs. Pearce Bros.

Date first visit — last visit — No. of Visits —

The 12 steel straps specified in the accompanying copy of Advice Notes were rolled from — charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests with satisfactory results.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions. Thickn. Ins.	Dimensions. Brdth. Ins.	Dimensions. Area. Ins.	Ultimate Stress. Total. Tons.	Ultimate Stress. Sq. Inch. Tons.	Exten. in 8 ins. %	Remarks.
	4 off 3.6 ½ × 11¼ × ⅝	L448		902	.63	1.66	1.045	29.74	28.4	24.0	M 5/5/85

Fee ..... £ : :

Expenses £ : :

£ : :

Wm Andrews

Surveyor, Lloyd's Register,

To be paid by Messrs. D. Colville & Sons Newcastle-on-Tyne

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

[6000—18/6/81.]

DUN110-0261 4/5/85

© 2019 Lloyd's Register Foundation