8813

REPORT of SURVEY for REPAIRS, &c.

Received in London Office, 17 OCT 1888

No. 8813 Date of Writing Report 188 Port of Glasgow

No. in Reg. Book. 29 Survey held at Glasgow Date, First Survey 4th Oct 1888 Last Survey 9th Oct 1888 (No. of Visits 3)

on the Iron B.K. "Earl Rosebery" Master Trampton

TONNAGE:— NET 1121 GROSS 1174 UNDER DK 1071

Built at Port Glasgow By whom Russell & Co When 1885. 3 (YEAR. MONTH.)

Owners W. J. Crawford Port belonging to

Owners' Address Greenock
(If not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Afloat Name of Dock Queens Destined Voyage Melbourne

Length of Poop ft.: of Forecastle ft.: of Raised Qr. Deck ft.: Moulded Depth ft. ins.
(If these particulars are not yet recorded in the Register Book.)

Classed — Years assigned, if a Wood Ship. — Character in Register Book.

Last Survey, No. 9584 Port Greenock

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.) Society's Freeboard (if assigned) as painted on Ship: in Summer ft. ins. in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Survey held at Greenock

In lieu of bestbower lost the following now put on board.

Cwt	Fathoms	Feet
1645.	34. 2 in 6	32. 0. 0. 0

Glasgow by Edinburgh.

Has replaced broken hawser 90 Fathoms 5½ hawser now put onboard

Insert Character precisely as in Register Book.

PRESENT CONDITION OF THE

Decks
Waterways
Rnings
Upp'r Dk. Beams & Fastenings
Low'r Dk. Beams & Fastenings
Sheerstrakes
Bilgestrakes
Topsides
Bottles

Plank (Bottom) & Counter
Treenails or Rivets
Breasthooks & Stemson
Transoms, Pointers & Crutches
Timbers of Frame at the openings
Ditto ditto at other places
Keelsons
Clamps & Shelfs

Ceiling
Rudder
Windlass & Capstan
Pumps
Cement (if Iron Ship)
Caulk'ng of Bot'm, D'k, & Watrwys
Copper, or Y.M. (State if on Felt.) When put on

Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors No. of
Cables
Hawsers & Warps
Standing & Running Rigging

Examined afloat

Anchors 3 @ 1 2 Kgood

Cables good

Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Cargo & Main Hatchways Hatches

General Observations, Opinion as to Class, Recommendation, &c.:

The above named part of equipment have now been examined onboard in completion of survey held as stated above

See Minute Book

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28)	£	:	:
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:
Certificate (if required) to be sent as per margin	£	:	:
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any)	£	:	:

Fees applied for, 188

Received by me, 188

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRIDAY 19 OCT 1888

Character assigned

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 10, Old Street, Goswell Road, London.

© 2019 Lloyd's Register Foundation

GLS156-026