"Baumben" & "Finland" Glasgow Reports No. 4529 & 4588.—

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 3364.

(Received at London Office, 15 FEB 86)

TESTS OF BOILER STEEL.

Tests of 4 Steel Plates manufactured by Messrs D. Colville & Sons of Motherwell for Boiler No. 198/9 to be constructed by Messrs Hutson & Corbett of Glasgow for Messrs A. McMillan & Sons & S No. ~~271/3~~ 240 & 2

Date first visit Feb 5th 1886 last visit ..... No. of visits .....

The ..... specified in the accompanying copy of Advice Notes were rolled from ..... charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests to a shearing from each plate.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions. Thickn. Ins.	Dimensions. Brdth. Ins.	Dimensions. Area. Ins.	Ultimate Stress. Total. Tons.	Ultimate Stress. Sq. Inch Tons.	Exten. in 8 ins. %	Remarks.
1	Outside Shell	C541		978	1.13	1.34	1.574	44.76	29.5	24.5	

M 25.2.86

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

Fee ..... £ : :

Expenses £ : :

£ : :

To be paid by

H. W. Dove

Surveyor, Lloyd's Register.

Glasgow 16.2.86

[T. & Son—6000—5/5/85.]

© 2021 Lloyd's Register Foundation

GLS205-0019