"Baumben" & "Finland" Glasgow Reports No. 4529 & 4588

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 3413.

(Received at London Office, 15 MAR 86)

TESTS OF BOILER STEEL.

Tests of 2 Steel Plates manufactured by Messrs D. Colville & Sons of Motherwell for Boiler No. 98/9 to be constructed by Messrs Anton & Corbett of Glasgow for Messrs A. McMillan & Sons S.S. No. 27173. 240 & 2

Date first visit Feb 18th 1886 last visit ..... No. of visits .....

The ..... specified in the accompanying copy of Advice Notes were rolled from ..... charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a shearing from each plate

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions. Thickn. Ins.	Brdth. Ins.	Area. Ins.	Ultimate Stress. Total. Tons.	Sq. Inch Tons.	Exten. in 8 ins. %	Remarks.
1	Back Tube Plate	K686		3684	·81	1·13	·914	24·32	26·5	26·54	

M 2-4-86

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

Fee ..... £ : :

Expenses £ : :

£ : :

To be paid by

A. W. Dove

Surveyor, Lloyd's Register.

Glasgow 9.3.86

[T. & Son—6000—5/5/85.]

© 2021 Lloyd's Register Foundation

GLS205-0021