51	Average Space between Beams	4ft 4ins	13	13	10½	10½	10½	8¾	Topsides	6½	6½	5½	Bilge Planks	4½	6½

Lloyds Register of British
and Foreign Shipping.

Greenock, 26th Novr 1869.

Adams Esqre
London.

Sir,

In answer to your note
of yesterday's date respecting the
when the doubling was put
on the Bottom of the "Asia"
No 3675; - We beg leave
to inform you that, it has not
been done yet. - We have
applied to the Builders, Messrs
J. Steele & Co. - also of Messrs
Duncan & Co. - part Owners
of Vessel - and they both
both "believe it to be the same as
"put on originally when she was
"built". -

In case this ~~matter~~ belief
may not be perfectly satisfactory
to you - the last mentioned Firm
have promised to make
enquiries of the Lunard Co
and let us know positively. -

With kind regards; and
trusting you are well. -

We remain,

Yours Very Truly -

pro: H. J. Boulds and J. Adams

J. Adams.

© 2020 Lloyd's Register Foundation

GRR295-0265

The Water-ways { Upper Deck ... Lower Deck not added of Pitch-pine. -