Received by Chief Surveyor 26/7/97. Received from Chief Surveyor

VESSEL'S NAME Ltd L. L. Meissen Report Ham No. 4317

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report 21/5/92.*)

Nature of Survey 1st Entry.

It is submitted that before this case receives the consideration of the Committee, the Surveyor should be requested to state if this vessel was supplied with 90 fathoms of 1 4/16" stream chain, or 90 fathoms of 4 3/4" steel wire, as required by the Rules, as no mention of this having been done is made upon the report.

Fr. b Hamburg 26/7/97.

E. J. M. 26/7/97

C. R. J.

Referred to the Chief Surveyor

© 2019 Lloyd's Register Foundation