7210

(Damage repairs &c)

REPORT of SURVEY for REPAIRS.

Rec'd 1st to 12th July 69

No. in Reg. Book. 252 ~~Sup. 25~~ 2/121

No. 3101 Survey held at Cardiff Date May 28th to June 28th 69

on the Iron S.S. "William Bank" Master George Bowen

Tonnage 691 460 built at Newcastle When built in 1869

By whom built Mitchell Owners Wm Bank

Port belonging to London Destined Voyage France from Cardiff

If Surveyed Afloat or in Dry Dock Mess^rs Hill & Sons Dry Dock Cardiff

Last Survey, No. 7028 Port ~~Newcastle~~ Iron Classed ~~A~~ A1

REPAIRS Placed in dry dock for repairs, Last Survey 4th Nov 1869 — Having been on shore on the Coast of France — Found on Survey, Keel broken in two or more places, about twenty feet from forward one Garboard plate forward, broken, one Garboard plate aft broken and one ends lips broken, all on the ~~Starboard~~ side — four plates aft, and four plates in the flat Starboard side bulged in and split two plates Port flat bulged in and split, some of Angle Irons broken, Keel removed for 47 feet in length from scarph to scarph, Piece welded in — 10 feet in length where broken Keel scarphed and Rebetted, Also several new Rivets in Keel where leaking at after part Angle Irons removed where broken, & replaced with new property shifted — All the plates removed replaced with new except one plate which has been rabbed out and replaced, All property Remitted as before Also Recemented where Cements disturbed to take out plates and Rivets —

Present Condition of the

Decks	Bent & good	Rivets	Between Decks good	Windlass and Capstan	Bent & good
Waterways	Do	~~Treenails~~		Pumps	Do
Comings	Do	Breasthooks and Stemson	Do	Boats	Do
Upper Deck Beams & Fastenings	Do	Transoms, Pointers, and Crutches	Do	Masts, Yards, &c.	Do
Lower Deck Beams & Fastenings	Do	Timbers of the Frame at the openings	Do	Condition, how ascertained	Do
Planksheers	Do	Ditto Ditto at other places	Do	Sails	Do
Sheerstrakes	All Iron	Keelsons	Do	Anchors No. of	3 B S S & 1 Kedge Do
Topsides	good	Clamps ~~and Shelfs~~	Stringers &c Do	Cables	Complete Do
Wales	Between	Ceiling	& Stringers Do	Hawsers and Warps	Sufficient Do
Plank (Bottom) and Counter	Iron	Rudder	Do	Standing & Running Rigging	Do
		Copper Painted	When put on entire		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. all good

This vessel being Surveyed after damage repairs completed. Again found in good condition, Fit to carry dry or perishable Cargoes; to and from all parts of the World, I am of opinion she may remain in Class A1

The Amount of Fee.....£ 2 : 0 : 0 is received by me,

June AMC

Special...for... £ : 5 : 0

damage Surveys and attendance while on Repairs Henry Hayne

Certificate (if required) : :

Committee's Minute 2nd July 18 69

Character assigned A1

record damage repairs

© 2019 Lloyd's Register Foundation