135544

ANNUAL SURVEYS.

No. 3368 Survey held at West Hartlepool Date 10th October 1874 Rec. 15/11/74

200 on the S.S. "Thetis" Master R. Milestone

Tonnage 531 830 Built at Sunderland When built 1866

By whom built Pile Owners J. J. Watt

Port belonging to N. Shields Destined Voyage

If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 11167 Port of Iron. Classed 80 A1

S.S. Std No 2-71 2.73

The present Condition of the

Decks	Good	~~Treenails~~	Quick Good	Windlass and Capstan	Good
Waterways (Gutter)	Good	Breasthooks and Stemson	not seen	Pumps	Good
Comings	Good	Transoms, Pointers, and Crutches	"	Boats	3 & Good
Upper Deck Beams & Fastenings	Good	~~Timbers of the Frame at the Openings~~	Good	Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings	Good	Ditto ditto at other places	Good	Sails	Good
~~Planksheers~~		Keelsons	Good	Anchors, No. of	3 Bowers 1 Stern 2 Kedges
Sheerstrakes	Good	~~Clamps and Shelfs~~		Cables	Good
Topsides	Good	Ceiling	Good	Hawsers and Warps	Good
Wales	Good	Rudder	Good	Standing and Running Rigging	Good
~~Plank~~ Plates (Bottom) and Counter	Good	Copper ——— When put on			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good

Now Dry Bottom cleaned down & coated with Paint & Black Varnish.

Is now in a good & efficient state, fit for the safe conveyance of Dry Perishable goods to & from all parts of the World & may in my opinion remain as now Classed 80 A1

S.S. Std No 2-71

Committee's Minute 16th October 1874

Character assigned 80 A

T. Gladstone

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____

on the _____ Master _____

Tonnage _____ Built at _____ When built _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors, No. of	
Sheerstrakes		Clamps and Shelfs		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing and Running Rigging	
Plank (Bottom) and Counter		Copper ——— When put on			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18

Character assigned _____

Certificate (if required).

3000—9/5/72.

© 2019 Lloyd's Register Foundation

IRON459-0191