SS No 2 14717 ~~34.7.91~~

REPORT of SURVEY for REPAIRS, &c.

(Recd 28.6.75)

No. in Reg. Book. **No.** 196 on the Iron SS Hawthorne

Survey held at London Date, first Survey _____ Last Survey June 21 1875

Master Croxon

TONNAGE under Tonnage Deck	698.73	Built at	Newcastle	When built	1861
Ditto of Spar Deck, or Awning Deck				YEAR.	MONTH. 8
Ditto of Poop, or Raised Qr. Dk.	44.80	Owners	J Fennick & Son	Port belonging to	London
Ditto of Houses on Deck	7.17				
Ditto of Forecastle		Residence			
Gross Tonnage	750.70				
Crew Space, as per Rule		By whom built	Palmer	Destined Voyage	
Register Tonnage, cut on Beam					
Engine Room	240.22	If Surveyed Afloat or in Dry Dock	Pontoon		
Reg. Tons as St'mer, cut on Bm.	510.48				

Official Number

Length of Poop — ft. Ditto, Forecastle Monkey ft. Ditto, Raised Quarter Deck ½ Poop 36 ft.

Classed Years assigned. A1 — Character in Register Book. 7.73

SS 6/ff 701-71

Last Survey, No. 11742 **Port** Iron

Length 199ft Breadth 28ft Depth 17.4

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

At the present time the Vessel placed on the Pontoon, the bilge keelings taken off on both sides all fore and aft. Likewise a great part off the double bottom. The Man hole doors of double bottom removed exposing both surfaces of plating &c which have been examined and found and the Cement adhering firmly to the Iron, but where worn thin has been recemented. Windlass unkeying & part of the Warding stripped, (being done in 1871) Chain Cable ranged on deck and examined. Plating scraped & chipped inside where practicable & painted & the outside scraped and painted. A few planks in the decks renewed and repaired

Present Condition of the

Decks	Good	~~Treenails~~ Rivets	Good	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	~~Timbers of~~ the Frame at the openings	"	Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings	"	~~Ditto~~ Ditto at other places	"	Condition, how ascertained	and
Planksheers	"	Keelsons	"	Sails	sufficient
Sheerstrakes	"	Clamps and Shelfs	"	Anchors No. of 3 Bs 1 Kedge	where
Topsides	"	Ceiling	"	Cables Com/Heb 225 fms	they
Wales	"	Rudder	"	Hawsers and Warps	could be
Plank (Bottom) and Counter	"	~~Copper~~ Painted When put on	now	Standing & Running Rigging	seen
		Caulking of Bottom, Deck, & Waterways	Good		

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as Classed and Marked SS No 2 1875 in the Register Book.

Lenhouse Martindale

The Amount of Entry Fee ... ...£ : : } received by me, } Hwms
30.6.7 Special ... ...£ 5 : 5 : } 30.7.1875 }
Certificate (if required) ... ...£ : : }
(Travelling Expenses, if any, £)

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 6th July 1875

Character assigned A1 S. S No 2-75

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

[2,000—20/11/74.]

© 2019 Lloyd's Register Foundation
IRON462-0102