15789A ~~35290~~

REPORT of SURVEY for REPAIRS, &c.

Rec 21.1.76

No. in Reg. Book. No. ✓ Survey held at London Date, first Survey " Last Survey January 20th 1876

46 on the S. S. Abydos Master Cummings

TONNAGE under Tonnage Deck	1113	Built at Glasgow	When built YEAR. 1871 MONTH. 3
Ditto of Spar Deck, or Awning Deck		Owners Globe S. S. Coy	Port belonging to London
Ditto of Poop		Residence "	"
Ditto of Raised Qr. Dk.		By whom built Lond & Gls. Coy	Destined Voyage Bombay
Ditto of Houses on Deck		If Surveyed Afloat or in Dry Dock	Afloat
Ditto of Forecastle			
Gross Tonnage	1119		
Crew Space, as per Rule			
Register Tonnage, cut on Beam			
Engine Room			
Reg. Tons as St'mer, cut on Bm.	715		

Official Number

Length of Poop " ft. Ditto, Forecastle " ft. Ditto, Raised Quarter Deck " ft. Classed | Years assigned. | Character in Register Book. 100 A 10-75

Last Survey, No. 15227 Port Iron

REPAIRS, OR EXAMINATION AS PER RULE

The whole of the ceiling and limber boards, all fore and aft, on both sides, removed. Cement examined and renewed where necessary. All floors, frames, stringers, inner surface of plating, bulkheads &c in fore and after hold, and bunkers, coated with paint after having been beaten and oxidation removed.

Completion of S. S. No 1. See Report No 15227

Present Condition of the Decks	Good	~~Treenails~~ Rivets	Good	Windlass and Capstan	Good and Sufficient where they could be seen
Waterways	"	Breasthooks and Stemson	"	Pumps	
Coomings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	~~Timbers~~ of the Frame at the openings	"	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	"	~~Ditto~~ Ditto at other places	"	Condition, how ascertained	
Planksheers Plating	"	Keelsons	"	Sails	
Sheerstrakes "	"	Clamps and Shelfs	"	Anchors No. of 3 B. 1 S. 2 K	
Topsides "	"	Ceiling	"	Cables	
Wales "	"	Rudder	"	Hawsers and Warps	
~~Plank~~ (Bottom) and Counter Good where seen		~~Copper~~ Paint When put on 1875		Standing & Running Rigging	
		Caulking of Bottom, Deck, & Waterways Good where seen			

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world and in my opinion eligible to remain as classed and marked S. S. No 1 – 1875

The Amount of Entry Fee ... ...£ : : : received by me, } Fe
22/1/76 Special ... ...£ 1 : 1 : } 14 Feb 1876
Certificate (if required) ... ...£ : :
(Travelling Expenses, if any, £)

James Bain
Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 15th February 1876

Character assigned 100 A

S. S. No 1 75

(The Surveyors are requested not to write on or below the space.)

© 2019 Lloyd's Register Foundation

IRON465-0054