18721

~~30298~~

ANNUAL SURVEYS.

22nd June, 77.

No. 1

No. in Reg. Book. 1213

Survey held at London — Date, first Survey 13 June — Last Survey 14th June 1877

on the S.S. "Ross Bay" — Master Mc Intyre

Tonnage 1413 1482 — Built at Glasgow — When built 1875 2 mo:

By whom built Robie — Owners Fatfield Cameron & Co

Port belonging to Glasgow — Destined Voyage

If Surveyed Afloat or in Dry Dock Limehouse dock

Last Survey, No. 13956 Port of Glasgow Iron — Classed — Years assigned. — Character in Register Book. 100 A1 2.75

Present Condition of the Decks		Treenails Rivets	
Waterways		Breasthooks and Stemson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	
Lower Deck Beams & Fastenings	Good	Ditto ditto at other places	
Planksheers		Keelsons	Good
Sheerstrakes		Clamps and Shelfs	
Topsides		Ceiling	
Wales		Rudder	
~~Plank~~ (Bottom) and Counter		Copper or Y.M. — When put on	
		Caulking of Bottom, Deck, & Waterways	
		Windlass and Capstan	
		Pumps	Good
		Boats	
		Masts, Yards, &c.	
		Condition, how ascertained	and
		Sails	
		Anchors, No. of	
		Cables	
		Hawsers and Warps	Complete
		Standing and Running Rigging	

Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers — Cargo and Main Hatchways — Hatches

General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated.
This Ship touched the ground off Orfordness Point on her last homeward voyage. No damage was sustained beyond starting a little cement about the forward part on Stbd side. The cement has been made good. The Ship appears eligible to remain as classed.

Committee's Minute — 26th June, 1877.

Character assigned 100 A 1

Thos Congdon
Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 5/ Paid 10 July 18 77

No. 2

No. in Reg. Book. 182

Survey held at London — Date, first Survey 18th June — Last Survey 15th June 1877

on the S.S. "Brigal" — Master Briggs

Tonnage ~~664~~ 598 ~~977~~ 948 — Built at Leith — When built 1862

By whom built Morton — Owners Tulley & Co

Port belonging to Hull — Destined Voyage

If Surveyed Afloat or in Dry Dock Regent dock

Last Survey, No. 17111 Port of Iron — Classed — Years assigned. — Character in Register Book. 90 ~~A1~~ S.S. No. 3-73 10-76

Present Condition of the Decks		Treenails Rivets	
Waterways		Breasthooks and Stemson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	
Lower Deck Beams & Fastenings	Good	Ditto ditto at other places	
Planksheers		Keelsons	Good
Sheerstrakes		Clamps and Shelfs	
Topsides		Ceiling	
Wales		Rudder	
Plank (Bottom) and Counter		Copper or Y.M. — When put on	
		Caulking of Bottom, Deck, & Waterways	
		Windlass and Capstan	
		Pumps	Good
		Boats	
		Masts, Yards, &c.	
		Condition, how ascertained	
		Sails	and
		Anchors, No. of	
		Cables	
		Hawsers and Warps	complete
		Standing and Running Rigging	

Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers — Cargo and Main Hatchways — Hatches

General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated.
This Vessel appears eligible to remain as classed

Committee's Minute — 26th June, 1877.

Character assigned 90 A 1

Thos Congdon
Surveyor to Lloyd's ~~Register~~ of British and Foreign Shipping.

Certificate (if required) ____ Paid ____ 18

3000—10/6/74

© 2019 Lloyd's Register Foundation

[RON]472-0412

Arras Bay

Fingal

© 2019
Lloyd's Register
Foundation