# ANNUAL SURVEYS.

1892/7

Rel 18/7/77

**No.** 4080 Survey held at Dundee. Date, first Survey July 19th Last Survey July 23rd 1877

No. in Reg. Book. 166. on the Iron Bk. "Bebington" Master at present. (Ril,

Tonnage 941 941 853. Built at Belfast. When built 1859-

By whom built Hickson Owners Shaw Saville & Co

Port belonging to Southampton. Destined Voyage Baltic.

If Surveyed Afloat or in Dry Dock In Dry Dock and afloat.

Last Survey, No. 15768 Port of Lon Classed

| Years assigned. | Character in Register Book. |
|---|---|
| * | A-1. |

Present Condition of the Decks Good

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

~~Plank~~ (Bottom) and Counter "

~~Treenails~~ Rivets, Sheerstrake Good

Breasthooks and Stemson Good.

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings "

Ditto ditto at other places ✓

Keelsons "

Clamps and Shelfs "

Ceiling in platt & main hold fair, at other parts of Ship Good.

Rudder Good and efficient.

Copper or Y.M. Cemt When put on 1870.

Caulking of Bottom, Deck, & Waterways Good.

S.S. Lo. R. No 1-74 2-76.

Windlass and Capstan Good.

Pumps "

Boats 4 R^o. "

Masts, Yards, &c. "

Condition, how ascertained from deck.

Sails Good.

Anchors, No. of 3 B. 13. 1 K. "

Cables "

Hawsers and Warps Good & Suff^t

Standing and Running Rigging Good & Suff^t

Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers " Cargo and Main Hatchways Good Hatches Good.

General Observations, Opinion as to Class, &c. The vessel placed on blocks, keel, bottom and sides cleaned down & examined; rebushed the rudder and fitted a plate gudgeon to post at lower part of neck of rudder; repaired the ceiling in main hold and recoated the bottom and sides.

This vessel is now in good Condition and eligible in my opinion to remain as Classed.

Committee's Minute 3rd August, 1877.

Character assigned *A1

J. L. Dinnette

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18____

---

**No.** _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____

No. in Reg. Book. _____ on the _____ Master _____

Tonnage _____ Built at _____ When built _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed

| Years assigned. | Character in Register Book. |
|---|---|
| | |

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelfs

Ceiling

Rudder

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute 18____

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18____

2000—15/5/77

© 2019 Lloyd's Register Foundation

IRON 473-0136