19814 Lrn.

S REGISTER OF BRITISH AND FOREIGN SHIPPING.

Rec'd 14/12/77

ENGINEER SURVEYOR'S REPORT ON MACHINERY.

ENGINES.

Compound Inverted Surface Condensing

J. Richardson & Sons

Built 18 74 At Hartlepool

Diameter of cylinder 29 & 55 Length of stroke 33"

Revolutions per minute About 65

Load draught off ½ stroke

Diameter of screw shaft 9"

Diameter of crank shaft journals 9"

Diameter of screw, ~~or of paddle wheel~~ 13.6

Pitch of screw 15.6

Blades, Four Total surface 60 sq feet

Feed pumps Two and sizes 2⅝ x 34" stke. Single Acting

Bilge pump from each compartment From Fore hold, Engine room & after well

Are all the bilge suction pipes fitted with roses Yes

No. of feed pumps Two and sizes 3¼ x 23/32 stke. Single Acting

What gauges are there attached to the engines and boilers ... Two steam, one vacuum

Description and size of Donkey Pumps ... No 1 pump 7½ dia x 9" stke. Double Acting, No 2 " 3½ " x 4" "

Where do they pump from ..... No 1 pumps from engine room bilge and from ballast tanks, No 2 pumps from each hold, Fore hold, Engine room & after well

No. of bilge injections 1 and sizes 4½"

Are they connected to air, or circulating pumps Circulating Pump

Is there a hand pump in the engine room Donkey works by hand

Can it be worked by the main engines No

Is there a deck hose of sufficient length to reach to any part of the vessel Yes

MAIN BOILERS.

No. Description Multitubular Fired at both ends

Built J. Richardson & Sons

Date 18 74 At Hartlepool

Working pressure 70 lbs

Tested by hydraulic pressure to 140 lbs, Date 10th Nov 1874

Description of super-heating apparatus ..... None

Can each boiler be worked separately Only one boiler in ship

Can the super-heater be shut off and the boilers worked separately No superheater

Description and area of safety valves on each boiler ..... Two spring safety valves, Combined area 35.4 sq in

No. of square feet of fire-grate surface in each boiler 58 sq feet

Are there separate blow off and brine cocks on each boiler, independent of those on the vessel's skin Yes

Are all pipes, cocks, roses, and pumps in connection with the machinery accessible at all times ..... All except suction pipes runs in holds when ship is loaded

DONKEY BOILER.

Description Vertical Water tubes in Furnace

Where fixed In Stokehold

Working pressure 50 lbs

Tested by hydraulic pressure to 120 lbs, Date 2nd Nov 1874

Description and area of safety valves Direct & Lever & weight. Total area 11.8 sq in

No. of square feet of fire grate 19.6 sq ft

PIPES, COCKS, AND CONNECTIONS.

Are all connections with the sea direct on the skin of the ship Yes

Are they Kingston valves or common cocks ... Stop valves and common cocks

Are they fixed sufficiently high on the ship's side to be seen without lifting the stoke hold plates ..... Yes

Are discharge pipes above or below the deep water line Below

Are they each fitted with a discharge valve on the plating of the vessel Yes

What pipes are carried through the bunkers None

How are they protected —

When were the stern tube, propeller, screw shaft, and all connections examined in dry dock New

Are the pipes, cocks, and valves arranged so as to prevent an unintentional connection between the sea and the bilge Yes

Is the screw shaft-tunnel water tight and fitted with a sluice door on bulkhead Tunnel not watertight. Sluice door fitted

J. Richardson & Sons
W. C. de Smith
Manufacturer.

I hereby certify that the whole of the above are correct particulars of the Machinery and Boilers of the Iron (or Wood) New (or Paddle) Steam Vessel "Valhalla" *owned by* J. Heron & Co

of the Port of West Hartlepool *of* 919.39 *Tons Register, and* 120 *Registered Horse Power, that they have been carefully inspected and examined by me at* Hartlepool *and found to be at this date, viz.,* 20th Dec. 18 74 *in good order and safe working condition.*

Amount of Fee for Survey ... ... £ 6 : 0 : 0
Certificate 0 - 5 - 0
Travelling Expenses, if any, £

James Main
Engineer Surveyor to Lloyd's Register of Shipping.

Rec'd 8.P.G.

76.]

©2019 Lloyd's Register Foundation
IRON475-0170