REPORT of SURVEY for REPAIRS.

No. 3765 Survey held at London Date Sept 22 1837
on the Ship London Master C. Lamb
Tonnage 239 Built at Sunderland When built 1833
By whom built Owners C. Lamb
Port belonging to London Destined Voyage Cape of Good Hope
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 3058 & 2220 Dated 1836 Class 10 A 1
Port of London

Repairs. At the present time upper strake off bottom vaulting unstripped over paper

The Surveyor to state the present Condition of

Upper Deck Fastenings	Good	Wales	Good
Spirketting		Counter	
Plank Shears		Plank and Treenails (Outside to the Water's Edge.)	
Topsides		Rudder	
Upper Deck with its Appendages		Windlass	
Lower Deck Fastenings		Capstan	

General Observations and Opinion, as required by the Instructions, In a very efficient state both as regards the hull & stores & recommended for present trip

W. Middleton

The Amount of Fee £ 1 : 1 : - is received by me.

Committee Minute Class 183 7

Character assigned 10 A 1

G. F. SEYFANG, PRINTER, FARRINGDON STREET, LONDON.

© 2019 Lloyd's Register Foundation

LON 601-0440