ANNUAL SURVEYS.

4914

No. 570 Survey held at London Date February 4th 1839

on the Ship Bengal Merchant Master Moncrief

Tonnage 531 Built at Calcutta When built 1818

By whom built _____ Owners Moncrief

Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Messrs Curlings Dry Dock

Original Survey, No. 1119, 2303 Port of London 1837 Classed ✠A.1

The Surveyor is required to state the present Condition of the

Decks		Breasthooks		Capstan	
Upper Deck Beams & Fastenings		Transoms		Pumps	
Lower Deck Beams & Fastenings	Good	Timbers of the Frame		Masts, Yards, &c.	
Spirketting		Topsides	Good	Sails	Good & Efficient
Plank Shears		Wales		Cables	
Waterways		Plank and Treenails (Outside to the Water's Edge)		Anchors No. of	
Hatchway Comings		Rudder		Standing & Running Rigging	
		Windlass		Copper 6 & 5c 1839	Smooth

General Observations and Opinion, as required by the Instructions, At the present time Topsides caulked Copper repaired Had part new upper deck of Teak at Calcutta 1838 She is in good Efficient condition & in my opinion is entitled to her present Class ✠A.1

George Bayley

Committee Minute 15th Feb 1839

Character assigned A.1 Asterisk

No. 742 Survey held at London Date February 4th 1839

on the Brig Mercury Master Dixon

Tonnage 326 Built at Shields When built 1814

By whom built _____ Owners J Brown

Port belonging to London Destined Voyage Coal Trade

If Surveyed Afloat or in Dry Dock Globe Dock

Original Survey, No. 325 Port of Newcastle 1835 Classed E.1

The Surveyor is required to state the present Condition of the

Decks		Breasthooks		Capstan	
Upper Deck Beams & Fastenings		Transoms		Pumps	
Lower Deck Beams & Fastenings	Fair	Timbers of the Frame		Masts, Yards, &c.	
Spirketting		Topsides	Fair	Sails	Efficient
Plank Shears		Wales		Cables	
Waterways		Plank & Treenails (Outside to the Water's Edge)		Anchors No. of	
Hatchway Comings		Rudder		Standing & Running Rigging	
		Windlass		Copper	Single

General Observations and Opinion, as required by the Instructions, At the present time 3 Planks shifted on Side & 2 on Starb.d Side above the Wale, Caulked from Keel up & overhauled In my opinion She is eligible to her present Class E.1

George Bayley

Committee Minute 15 Feb 1839

Character assigned E.1

C. F. SEYFANG, PRINTER, FARRINGDON STREET, LONDON.

© 2019 Lloyd's Register Foundation

LONG-0276