ANNUAL SURVEYS.

11962

No. 342 Survey held at London Date Oct 6 to 14 1845

on the Bk Alford Master Fullerton Barnet

Tonnage 295 Built at Greenock When built 1836

By whom built _____ Owners Rintoul & Co

Port belonging to Glasgow Destined Voyage Canton

If Surveyed Afloat or in Dry Dock Fletchers Dock

Last Survey, No. 1611 Port of Clyde Classed 11A1

The Surveyor is required to state the present Condition of the

Decks	Good	Transoms	Sound	Capstan	Good
Upper Deck Beams & Fastenings	"	Timbers of the Frame	Sound & Sheerings	Pumps	"
Lower Deck Beams & Fastenings	"	Topsides	Good	Masts, Yards, &c.	Mainmast Sore
Spirketting	"	Wales	"	Sails	Goo sails
Plank Shears	"	Counter	"	Cables	Good Sound
Waterways	"	Plank and Treenails (Outside to the Water's Edge.)	"	Anchors No. of	3 Bowes 1 Sln 2 Kedges
Hatchway Comings	"	Rudder	"	Standing & Running Rigging	Good
Breasthooks	"	Windlass	"	Copper	Yellow Metal

General Observations and Opinion, as required by the Instructions, Goo Selanks in the Bottom, the Keel being scarfed, Goo binding bolts renewed with Yellow Metal from the Stern Post aft, Goo Selanks in Shoes, caulked from the keel to the wales & sheathed with Yellow Metal upper course of Selt and below over Lapher and is in an efficient State to retain her

Committee Minute 17th Oct 1845 present class, Character assigned 11 A 1 renewed

W Woodgate
J Fletcher

No. 494 Survey held at London Date Oct 15th 1845

on the Bk Claudia Master Peake

Tonnage 336 Built at Sunderland When built 1844

By whom built _____ Owners Collings & Co

Port belonging to London Destined Voyage Demerara

If Surveyed Afloat or in Dry Dock Day Docks & Afloat

Last Survey, No. 10613 Port of London Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Good	Transoms	Sound	Capstan	Good
Upper Deck Beams & Fastenings	"	Timbers of the Frame	Sound	Pumps	"
Lower Deck Beams & Fastenings	"	Topsides	"	Masts, Yards, &c.	"
Spirketting	"	Wales	"	Sails	Well found
Plank Shears	"	Counter	"	Cables	"
Waterways	"	Plank and Treenails (Outside to the Water's Edge)	"	Anchors No. of	"
Hatchway Comings	"	Rudder	"	Standing & Running Rigging	Good
Breasthooks	"	Windlass	"	Copper	1844 "

General Observations and Opinion, as required by the Instructions, Bottom examined and is in all respects in an efficient State to retain her present class

W Woodgate

Committee Minute 17th Oct 1846

Character assigned 12 A 1

© 2019 Lloyd's Register Foundation

C. F. SEYFANG, PRINTER, 57, FARRINGDON STREET, LONDON.

LON619-0454