16099

# REPORT of SURVEY for REPAIRS.

Reclassing

No. Survey held at Londou Date 27th June 1850

on the Schr "Flora" Master John Pavey

Tonnage 151 Built at Brudport When built 1826

By whom built _____ Owners John Pavey

Port belonging to Londou Destined Voyage _____

If Surveyed Afloat or in Dry Dock Deutord ways
pt AB Ton 34 Sipts 44

Last Survey, No. 366 Port Waterford Classed 10 R.J. 47 Ship omitted

REPAIRS at present laid aground for Survey - butts of bottom Caulkd Sheerstrakes Caulkd and Rudder bands Refastened bottom Stocked and left Clinker

Present Condition of the

| | | | | | |
|---|---|---|---|---|---|
| Decks | | Treenails | | Windlass and Capstan | Good |
| Waterways | | Breasthooks and Stemson | | Pumps | — — |
| Comings | | Transoms, Pointers, and Crutches | | Boats | two — — |
| Upper Deck Beams & Fastenings | Good | Timbers of the Frame | Large | Masts, Yards, &c. | Good |
| Lower Deck Beams & Fastenings | for | Keelsons | Large | Sails | 2 Suits |
| Plankshеers | Class | Clamps and Shelfs | | Anchors No. of | 2 1 1 |
| Sheerstrakes | Recommd | Ceiling | | Cables | Sufficient |
| Topsides | | Rudder | bands Refastd | Hawsers and Warps | do |
| Wales | | Copper | None When put on | Standing & Running Rigging | do |
| Plank (Bottom) and Counter | | | | | |

General Observations and Opinion, This Vessel is in Present Condition in my Opinion fit for the Safe Conveyance of Dry and Perishable Cargoes and is Eligible to be Classed

The Amount of Fee.....£1 : : is received by me, T. Ritchie

Special..... : :

Certificate (if required) : 5 :

Committee's Minute 2nd July 1850

Character assigned A 1

© 2019 Lloyd's Register Foundation
LON 628-0 408