1803

REPORT of SURVEY for REPAIRS.

Rec 27/1/53

No. 1 Survey held at London Date Dec 21 1852 to Jan 7 1853

No. 80 on the Bark "Waterhen" Master W Dodds

Tonnage 355 Built at Hull When built 1825

By whom built _____ Owners J Robertson

Port belonging to London Destined Voyage Port Phillip

If Surveyed Afloat or in Dry Dock in Mess^rs Fletchers Dock afloat

---

1st Survey, No. 548 Port Gloucester Classed * A. 1 SS. 1853

REPAIRS at present Zinc Sheathing nailed two Thirds all round. the Raft Ports Refitted — the hold Ceiling repaired — five Pairs of iron hanging Knees fitted to the hold beams iron bolted — the after piece of hog Keelson trunnied over and fitted — new Letters (Rapkons Patent) fitted to the Rudder — new lower Riggings fitted to fore & main Masts —

It is Remarkable that Capt. W Dodds has Commanded this Ship for Twenty years

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Quarterways		Breasthooks and Stemson		Pumps	
Planings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings		Keelsons	Good	Sails	&
Sheerstrakes	Good	Clamps and Shelfs		Anchors No. of	Sufficient
Waterstrakes		Ceiling		Cables	
Topsides		Rudder new letter		Hawsers and Warps	
Bottles		Copper		Standing & Running Rigging	
Bilge (Bottom) and Counter		When put on	June 1850 Part 1853		

General Observations and Opinion,

This Vessel appears in efficient Condition and fit to remain as Classed

The Amount of Fee.....£ : : is received by me, J W Fletcher

Special..... 1 : 1 : —

Certificate (if required) : 10 : —

Committee's Minute 28 June 1853

Character assigned A 1 Special £ 1 — 1

© 2019 Lloyd's Register Foundation
LON 632-0462