18212

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 457 Survey held at London Date May 6th 1853

on the Ship "John Wickliffe" Master Mr Hudson

Tonnage 543 661 Built at Dumbarton When built 1841

By whom built — Owners M E Corner & Co

Port belonging to London Destined Voyage Quebec & back to London

If Surveyed Afloat or in Dry Dock E I Dock

pt F & cl 50 SFM & pt F 50 pt NW & Srprs 50

Last Survey, No. 15,969 Port London 15969 Classed 10 ~~R~~ 50 Class omitted ~~expunged~~

REPAIRS

At the present time the ceiling repaired in various places with about 120 feet of plank, new timbers and fastenings to the Head.

Present Condition of the

Decks	good for her class	Treenails	good her class	Windlass and Capstan	efficient
Waterways	do	Breasthooks and Stemson	do	Pumps	do
Comings	do	Transoms, Pointers, and Crutches	do	Boats	do
Upper Deck Beams & Fastenings	Seam	Timbers of the Frame where seen	do	Masts, Yards, &c.	do
Lower Deck Beams & Fastenings	do	Keelsons	do	Sails	do
Planksheers	good for her class	Clamps and Shelfs	do	Anchors No. of 311	do
Sheerstrakes	do	Ceiling	do	Cables	do
Topsides	do	Rudder	do	Hawsers and Warps	now lapp new H.S. & warp 5 in ~~with hose new Hempen Stuart~~
Wales	do	Copper	Metal When put on 1850	Standing & Running Rigging	do 15/1/53
Plank (Bottom) and Counter	do				

General Observations and Opinion,

She is in good Condition fit for the conveyance of dry and perishable Cargos and may be reclassed A 1 &c

Courtenay

The Amount of Fee.....£ 3 : — : — is received by me, [illegible]

Special..... : :

Certificate (if required) : :

Committee's Minute 20 May 1853

Character assigned [illegible] 1 [illegible]

[illegible]

© 2019 Lloyd's Register Foundation

LON 633-0148