ANNUAL SURVEYS.

18409

No. 49 on the Ship Cambridge — Survey held at London — Date July 28 & August 3 1853

Tonnage 1036 / 1225 — Built at Miramichi — Master Wilson

By whom built — When built 1851

Port belonging to Liverpool — Owners Palmer Hoare & Sons & Co

If Surveyed Afloat or in Dry Dock — Destined Voyage Calcutta

Last Survey, No. 11440 — Port of Liverpool — Classed 6 A 1 / 52

The present Condition of the

Decks: Good
Waterways: Good where seen
Comings: Do
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
} Good where seen

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame
Keelsons
Clamps and Shelfs
Ceiling
} Good where seen
Rudder: Good
Copper — When put on

Windlass and Capstan: Good
Pumps
Boats
Masts, Yards, &c.
Sails
Anchors No. of
Cables
Hawsers and Warps
} Good and Sufficient
Standing & Running Rigging: Good

General Observations and Opinion, The Main Hatch Beam being out and opened very much with heat from the cargo, also one of lower deck beams has been made secure by clamping and fotings. The beams have been made secure by clamping and fotings. The Yellow Metal patched at present. She appears to be in good condition and fit to remain as classed

Committee's Minute: 12th Aug 1853

Character assigned: 6 A 1

M. M. Intyre

Certificate (if required)

No. 811 on the Ship Crystal Palace — Survey held at London — Date July 29th 1853

Tonnage 480 / 494 — Built at Teignmouth — Master Marrasoto

By whom built — When built 1853

Port belonging to London — Owners J. Sedgetto

If Surveyed Afloat or in Dry Dock — Destined Voyage

Last Survey, No 17584 — Port of London — Classed 11 A 1 / 52

The present Condition of the

Decks: Good
Waterways: Do
Comings: Do
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
} Good

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame
Keelsons
Clamps and Shelfs
Ceiling
Rudder
} Good
Copper Yellow Metal — When put on 1852

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Sails
Anchors No. of
Cables
Hawsers and Warps
} Good & Sufficient
Standing & Running Rigging

General Observations and Opinion, This vessel when seen in Dock for the purpose of sighting the bottom found her in good condition and fit to remain as classed

Committee's Minute: 19th Aug 1853

Character assigned: 11 A 1

M. M. Intyre

Certificate (if required)

© 2019 Lloyd's Register Foundation

SEYFANG AND CO. PRINTERS, 57, FARRINGDON STREET, LONDON.

LOU 633-0348